

X-RAY EMERGENCY PROCEDURES

Individuals who suspect that they have been exposed to the direct beam from any x-ray producing equipment shall:

1. Immediately turn the equipment off.
2. Call the Radiation Safety Office at **231-5364** (before 5pm) or the Virginia Tech Police at **911** (after 5pm, or on weekends).
3. Notify one person from the laboratory line of authority.
4. Remain in the area until the arrival of the Radiation Safety Officer, or his designee.

EMERGENCY CONTACTS

Laboratory Authority	Dr. Ross Angel 1050 Derring Hall	1-7974	953-0147
Secondary Contact	Dr. Carla Slebodnick 1050 Derring Hall	1-7974	552-1662
Other Contact	Dr. Jing Zhao 3052 Derring Hall	1-5539	320-1587
Other Contact	Dr. Nancy Vogelaar 5094 Derring Hall	1-2093	239-5962 (cell)

EMERGENCY TELEPHONE NUMBERS

	8am-5pm	After 5pm
Radiation Safety Office	1-5364	911
Hazardous Material Safety	1-8758	911
Virginia Tech Police	911	911
Rescue Squad	911	911
Fire	911	911